

To:

John Fortman

Attn: District One

From:

John D. Baranzelli

Subject:

—Pavement-Design

Date:

July 12, 2012

FAU Route 1321 (IL 19 – Irving Park Road) Section 32 WRS-5 Du Page County At York Road

We have reviewed the pavement design for the above captioned section submitted to BDE on May 24, 2012. The intersection is considered "high stress" because MU ADT > 200 vehicles. The life cycle cost analysis favored the rigid design by over 10%. The approved pavement design is as follows:

IL 19 - Irving Park Road [New Construction]

10.25 inches of jointed PCC pavement with tied PCC curb & gutter 12 inches of Aggregate Subgrade Improvement Geotechnical Fabric

IL 19 - Irving Park Road [Widening]

13 inches of Composite Pavement with tied PCC curb & gutter

- 1.75 inches of Polymerized HMA Surface Course Mix "F", N90
- 2.25 inches of Polymerized HMA Binder Course IL 19.0, N90
- 9 inches of PCC Base Course

12 inches of Aggregate Subgrade Improvement Geotechnical Fabric

IL 19 - Irving Park Road [Existing Pavement Resurfacing]

Cold Milling of Existing HMA Pavement, 4 inches minimum

4 inches HMA Resurfacing

1.75 inches of Polymerized HMA Surface Course Mix "F", N90 2.25 inches of Polymerized HMA Binder Course IL 19.0, N90

York Road [New Construction]

10.25 inches of jointed PCC pavement with tied PCC curb & gutter

12 inches of Aggregate Subgrade Improvement

York Road [Widening - South of Reconstruction]

13.25 inches of Composite Pavement with tied PCC curb & gutter 1.75 inches of Polymerized HMA Surface Course Mix "F", N90

2.25 inches of Polymerized HMA Binder Course IL 19.0, N90

9.25 inches of PCC Base Course

12 inches of Aggregate Subgrade Improvement

York Road [Widening - North of Reconstruction]

12.25 inches of Composite Pavement with tied PCC curb & gutter

1.75 inches of Polymerized HMA Surface Course Mix "F", N90

2.25 inches of Polymerized HMA-Binder Course IL 19.0, N90

8.25 inches of PCC Base Course

12 inches of Aggregate Subgrade Improvement

York Road [Existing Pavement Resurfacing]

Cold Milling of Existing HMA Pavement, 4 inches minimum

4 inches HMA Resurfacing

1.75 inches of Polymerized HMA Surface Course Mix "F", N90

2.25 inches of Polymerized HMA Binder Course IL 19.0, N90

If you have any questions, please contact Paul Niedernhofer at (217) 524-1651.

Catherine Kibble

Attn:

Serin Keller

From:

Jose Dominguez

By: Melchor Mangoba/Jenpai Chang

Subject:

Pavement Analysis*

Date:

July 13, 2012

*Route: FAU 1321 (IL 19 (Irving Park Road))

Limits: at York Road Contract No.: 60B42

Section: 32 WRS-5 County: DuPage Job No.: D-91-332-06

Letting: 08CY12

We have received our approved pavement design for the above captioned location in a July 12th, 2012 memo from our Central Office. Please note that the total pavement area for reconstruction exceeds 4,750 Square Yards. The improvement involves the following scope of work:

- a.) Pavement reconstruction of approximately 4,700 square yards, pavement widening and of approximately 944 square yards and resurfacing of IL 19 (Irving Park Road) at York Road from the Bensenville Ditch to just passed Garden Avenue.
- b.) Pavement reconstruction of approximately 6,400 square yards, widening of approximately 1,700 square yards and resurfacing of York Road from just west of Roosevelt Avenue to just west of Gateway Road.

A 20 year pavement analysis was performed for the pavement reconstruction and widening of IL 19 (Irving Park Road). We recommend a mechanistic-rigid pavement design for the pavement reconstruction and full depth HMA pavement for the pavement widening. The intersection of IL 19 and York Road is considered "high stress" as the design lane MU ADT exceeds 200 vehicles at the stop controlled intersection. District 1 recommends rigid pavement at "High Stress" intersections to be built at a minimum 150 ft back from the location of the stop bar. The recommended pavement is:

a.) IL 19 (Irving Park Road)

Pavement Reconstruction Tied PCC Curb and Gutter 10 1/4" PCC Pavement (Jointed) 1 12" Aggregate Subgrade Improvement Geotechnical Fabric

The life cycle cost analysis favors PCC pavement by 11%.

Catherine Kibble/Serin Keller July 13, 2012 Page 2

A segmental pavement analysis was performed for the pavement widening on IL 19 (Irving Park Road). We recommend using a composite pavement design matching into the existing pavement.

Pavement Widening
Tied PCC Curb and Gutter

13" Composite Pavement

1 3/4" Polymerized HMA Surface Course, Mix "F", N90 2 2 1/4" Polymerized HMA Binder Course, IL-19.0, N90 3

9" PCC Base Course 4

12" Aggregate Subgrade Improvement Geotechnical Fabric

Existing Pavement Resurfacing

Cold Milling of Existing HMA Pavement

4" Minimum more, if necessary

4" HMA Resurfacing

1 3/4" Polymerized HMA Surface Course, Mix "F", N90 2

2 1/2" Polymerized HMA Binder Course, IL-19.0, N90 3

A 20 year pavement analysis was performed for the pavement reconstruction and widening of York Road. We, recommend a mechanistic-rigid pavement design for the pavement reconstruction and full depth HMA pavement for the pavement widening. The intersection of IL 19 and York Road is considered "high stress" as the design lane MU ADT exceeds 200 vehicles at the stop controlled intersection. The recommended pavement is:

b.) York Road*

Pavement Reconstruction
Tied PCC Curb and Gutter
10 1/4" PCC Pavement (Jointed) 1
12" Aggregate Subgrade Improvement

The life cycle cost analysis favors PCC pavement by 11.2%.

A segmental pavement analysis was performed for the pavement widening on York Road. We recommend using a composite pavement design matching into the existing pavement south of the reconstruction and an HMA (full depth) matching the existing pavement north of the reconstruction. A 4 inch resurfacing will be used for both sections.

Pavement Widening (south of reconstruction)

Tied PCC Curb and Gutter

13 1/4" Composite Pavement

1 3/1" Polymerized HMA Surface Course, Mix "F", N90 2

2 1/4" Polymerized HMA Binder Course, IL-19.0, N90 3

9 1/4" PCC Base Course

12" Aggregate Subgrade Improvement

Catherine Kibble/Serin Keller July 13, 2012 Page 3

Pavement Widening (north of reconstruction)
PCC Curb and Gutter

17" HMA (Full Depth) Pavement

1 3/4" Polymerized HMA Surface Course, Mix "F", N90 2

2 1/4" Polymerized HMA Binder Course, IL-19.0, N90 3

13" HMA Binder Course, IL-19.0, N90 6

12" Aggregate Subgrade Improvement

Existing Pavement Resurfacing

Cold Milling of Existing HMA Pavement

4" Minimum more, if necessary

4" HMA Resurfacing

1 3/4" Polymerized HMA Surface Course, Mix "F", N90 2

2 1/4" Polymerized HMA Binder Course, IL-19.0, N90 3

1 Designer Note 1: To be paid as pay item #42000506 - "PORTLAND CEMENT CONCRETE PAVEMENT 10 1/4" (JOINTED)", paid in square yards.

² Designer Note 2: To be paid as pay item #40603595 - "POLYMERIZED HOT-MIX ASPHALT SURFACE COURSE, MIX "F", N90", paid in tons.

³ Designer Note 3: To be paid as pay item #40603240 - "POLYMERIZED HOT-MIX ASPHALT BINDER COURSE, IL-19.0 N90", paid in tons.

⁴ <u>Designer Note 4:</u> To be paid as pay item #35300400 - "PORTLAND CEMENT CONCRETE BASE COURSE, 9", paid in square yards.

⁵ Designer Note 5: To be paid as pay item #35300405 - "PORTLAND CEMENT CONCRETE BASE COURSE, 9 1/4", paid in square yards.

6 Designer Note 6: To be paid as pay item #35501336 - "HOT-MIX ASPHALT BASE COURSE, 13" ", paid for in square yards.

* York Road is subject to local jurisdiction concurrence. The work south of IL 19 (Irving Park Road) is subject to Village of Bensenville. The pavement design north of IL 19 (Irving Park Road) is per the request of DuPage County. York Road is a "High Stress" intersection since the design lane MU ADT exceeds 200 vehicles. District 1 recommends rigid pavement. However, if the municipality elects to use HMA, we recommend using Mix "F" N90 at "High Stress" intersections. Either selection is preferred to be built at a minimum 150 ft back from the location of the stop bar.

If you have any questions or need additional information, please contact Jenpai Chang, Acting Pavement Design Engineer, at (847)705-4432.

By: Jose A. Dominguez, P.F. Project Support Engineer

To: John D. Baranzelli, PE

Attn: Paul R. Niedernhofer

From: Diane O'Keefe

By: Jose Dominguez

Subject: Pavement Analysis*

Date: March 21, 2012

*Route: FAU 1321 (IL 19 (Irving Park Road))

Section: 32 WRS-5 Limits: at York Road County: DuPage Job No.: D-91-332-06 Contract No.: 60B42

Letting: 08CY12

We are submitting the payement analysis for the above captioned location for your review and approval. Please note that the total pavement area for reconstruction exceeds 4,750 Square Yards. The improvement involves the following scope of work:

- a.) Payement reconstruction of approximately 4,700 square yards, payement widening and of approximately 944 square yards and resurfacing of IL 19 (Irving Park Road) at York Road from the Bensenville Ditch to just passed Garden Avenue.
- b.) Pavement reconstruction of approximately 6,400 square yards, widening of approximately 1,700 square yards and resurfacing of York Road from just west of Roosevelt Avenue to just west of Gateway Road.

A 20 year pavement analysis was performed for the pavement reconstruction and widening of IL 19 (Irving Park Road). We recommend a mechanistic-rigid pavement design for the pavement reconstruction and full depth HMA pavement for the pavement widening. The intersection of IL 19 and York Road is considered "high stress" as the design lane MU ADT exceeds 200 vehicles at the stop controlled intersection. The recommended pavement is:

a.) IL 19 (Irving Park Road)

Payement Reconstruction Tied PCC Curb and Gutter 10 1/4" PCC Pavement (Jointed) 12" Aggregate Subgrade Improvement Geotechnical Fabric

The life cycle cost analysis favors PCC pavement by 11%.

John D. Baranzelli, PE March 21, 2012 Page 2

A segmental pavement analysis was performed for the pavement widening on IL 19 (Irving Park Road). We recommend using a composite pavement design matching into the existing pavement.

Pavement Widening

Tied PCC Curb and Gutter

13" Composite Pavement

1 3/4" Polymerized HMA Surface Course, Mix "F", N90

2 1/4" Polymerized HMA Binder Course, IL-19.0, N90

9" PCC Base Course

12" Aggregate Subgrade Improvement

Geotechnical Fabric

Existing Pavement Resurfacing

Cold Milling of Existing HMA Pavement

4" Minimum more, if necessary

4" HMA Resurfacing

1 34" Polymerized HMA Surface Course, Mix "F", N90

2 1/4" Polymerized HMA Binder Course, IL-19.0, N90

A 20 year pavement analysis was performed for the pavement reconstruction and widening of York Road. We, recommend a mechanistic-rigid pavement design for the pavement reconstruction and full depth HMA pavement for the pavement widening. The intersection of IL 19 and York Road is considered "high stress" as the design lane MU ADT exceeds 200 vehicles at the stop controlled intersection. The recommended pavement is:

b.) York Road*

Pavement Reconstruction

Tied PCC Curb and Gutter

10 1/4" PCC Pavement (Jointed)

12" Aggregate Subgrade Improvement

The life cycle cost analysis favors PCC pavement by 11.2%.

A segmental pavement analysis was performed for the pavement widening on York Road. We recommend using a composite pavement design matching into the existing pavement south of the reconstruction and an HMA (full depth) matching the existing pavement north of the reconstruction. A 4 inch resurfacing will be used for both sections.

Pavement Widening (south of reconstruction)

Tied PCC Curb and Gutter

13 ¹/₄" Composite Pavement

1 34" Polymerized HMA Surface Course, Mix "F", N90

2 1/4" Polymerized HMA Binder Course, IL-19.0, N90

9 1/4" PCC Base Course

12" Aggregate Subgrade Improvement

John D. Baranzelli, PE March 21, 2012 Page 3

Pavement Widening (north of reconstruction)
PCC Curb and Gutter

12 1/4" HMA (Full Depth) Pavement

1 3/4" Polymerized HMA Surface Course, Mix "F", N90

2 1/4" Polymerized HMA Binder Course, IL-19.0, N90

8 1/4" PCC Base Course

12" Aggregate Subgrade Improvement

Existing Pavement Resurfacing

Cold Milling of Existing HMA Pavement

4" Minimum more, if necessary

4" HMA Resurfacing

1 3/4" Polymerized HMA Surface Course, Mix "F", N90

2 1/4" Polymerized HMA Binder Course, IL-19.0, N90

*Designer Note 1: York Road is subject to local jurisdiction concurrence. The work south of IL 19 (Irving Park Road) is subject to Village of Bensenville. The work north of IL 19 (Irving Park Road) is subject to DuPage County.

If you have any questions or need additional information, please contact Mr. Tom Matousek at (847)705-4255.

By: Jose A. Dominguez, P.E. Project Support Engineer



Illinois Department of Transportation

To:

Diane M. O'Keefe

Attn: District One

From:

Scott E. Stitt Santague

Subject:

Pavement Design

Date:

January 7, 2011

DECEIVE

DIST. ONE - DESIGN

FAP Route 345 (Irving Park Road)
Cook/Du Page Counties
From east of York Road to east of Taft Road

We have reviewed the pavement selection for the above captioned section, which was submitted January 7, 2010. Due to the high number of MU's and construction being provided by the City of Chicago, a rigid pavement design will be utilized.

The approved pavement design for is as follows:

IL 19 (Irving Park Road)

10.25 inches of jointed PCC pavement with tied PCC curb & gutter 12 inches aggregate subgrade

Taft Road (North)

10.25 inches of jointed PCC pavement with tied PCC curb & gutter 12 inches aggregate subgrade

Taft Road (South)

10.25 inches of jointed PCC pavement with tied PCC curb & gutter 12 inches aggregate subgrade

If you have any questions, please contact Paul Niedernhofer at (217) 524-

Asst. to the D.E. Engr. Proj. Imp. Construction Local Roads Materials EEO Engr. Prog. Dev. Design Land Acq Programming Public Info Engr. Oper. Elect. Oper. Maintenance Traffic Administration To:	┡┋	9	- Agt
;	$\left\{ \cdot \right\}$	††	\prod
Asst. Dpty. Sec. Olty. Compliance	\dashv		

Full-Depth HMA Pavement	JPC Pavement
$Use \ TF \ flexible = 11.09$ $PG \ Grade \ Lower \ Binder \ Lifts = 12.034.224 \ (Fig. 53-4.R)$ $HMA \ Mixture \ Temp. = 12.04 \ deg. \ F \ (Fig. 54-5.C)$ $Design \ HMA \ Mixture \ Modulus \ (E_{HMA}) = 720 \ ksi \ (Fig. 54-5.D)$ $Design \ HMA \ Strain \ (\varepsilon_{HMA}) = 60 \ (Fig. 54-5.E)$	Use TF rigid = 14.79 Edge Support = Shoulder or C.&G. Rigid Pavt Thick = 10.25 in: (Fig. 54-4!E) CRC Pavement
Full Depth HMA Design Thickness = 12.25 in. (Fig. 54-5.F) Limiting Strain Criterion Thickness = 12.25 in. (Fig. 54-5.I) Use Full-Depth HMA Thickness = 12.25 inches	Use TF rigid = 14.79 IBR value

RECONSTRUCTION ONLY (SUPPLEMENTAL) PAVEMENT DESIGN CALCULATIONS				
HMA Overlay of Rubblized PCC	Unbonded Concrete Overlay			
Use TF flexible = 11.09	Review 54-4.03 for limitations and special considerations.			
District = 335066 HMA Overlay Design Thickness = 10.50 in (Fig. 54-5.U)	UPCP Thickness:= NA inches			

CONTACT BMPR FOR ASSISTANCE

DESIGN TABLES FROM BDE MANUAL CHAPTER 54 - PAVEMENT DESIGN Class | Roads Class | Roads Class | II Roads Class | II Roads 4 | Janes or more 2 | Janes with ADT > 2000 2 | Janes 2 | Janes Part of a future 4 | Janes or more One way Street with ADT <= 3500</td> (ADT 750 -2000) (ADT < 750)</td> Min. Str. Design Traffic (Fig 54-2.C)

•	Min. Str. Design Traffic (Fig 54-2.C)				
Facility Type	PV	SÚ	MU		
Interstate or Supplemental Freeway	0 .	500	1500		
Other Marked State Route	0	250	750		
Unmarked State Route	No Min	No Min	No Min		

·	Traffic Factor ESAL Coefficients				
	Rigid (F	ig. 54-4.C)	Flexible (Fig. 54-5.B)		
Class	Csu	Cmu	Csu	Cmu	
经定款 医皮肤性皮肤 建苯胺基乙基 医外部	143.81	696.42	132.50	482.53	
ACCURATION AND AND ADDRESS OF A PARTY OF THE	135.78	567.21	112.06	385.44	
111	129.58	562.47	109.14	384.35	
IV	129.58	562.47	109.14	384.35	

One-Way Streets			
ADT	Class		
0 - 3500	- 11		
>3501	1		

Class Table for			
2 or 3 lanes			
(not future 4 lane &			
not one-way street)			
ADT	Class		
0 - 749	IV		
750 - 2000	10		
>2000	ĪI		

	Design Lane Distribution Factors For Structural Design Traffic (Fig. 54-2.B)					54-2.B)
	Rural				Urban	
Number of Lanes	Р	S	М	Р	S	М
1 Lane Ramp	100%	100%	100%	100%	100%	100%
2 or 3	50%	50%	50%	50%	50%	50%
4	32%	45%	45%	32%		45%
6 or more	20%	40%	40%	8%	37%	37%

MECHANISTIC PAVEMENT DESIGN

	21-Mar-12			Route	IL 19@York Ro	[
7.446	SIP			Section	32 WRS-5	
Checked by:				•	age County	
Class	I	Roads and Stre	eets	Location	York Rd	
Urban	X	Rural				P
Limits of Analys	sis	Station 394	A-14-5	treater with the felder to a Car	16 55 55	
		Length 87	<u>78</u> Feet	<u>0.17</u>	Miles	
Structural Desig	on Traffic	Doro	ont of CDT i	n Design Lane		
PV =	~	Ferti	P = 87.009	•		
	30798		<u>-</u>			
SU =	<u>2832</u>					
MU =	<u>1770</u>		U = 5.00%	-		
M	INIMUM SUI	BGRADE SUPP	ORT RATING	- "POOR"		ere.
					•	
	, , , , , , , , , , , , , , , , , , , ,	**************************************	M M = M 		عد عدد حد به دا اردو بها حبرا شوه بين براط باب ايم خواه بان او العد مو عدد عد عد عد عد عد عد عد عد 	
			•			
<u>Flexible Paveme</u>	ent Design	Actual T	$F_F = 11.09$	Minimu	$m TF_F = 3.56$	
		v.			•	
	1270	i describito sell'aurante.	Selected De	esign AC Type	ELECTRICALITICS SETURE:	
Design AC Mixt	ure Temp	74 °F		Design E _{AC}	725 KSI	
Design AC M	icrostrain	- <u>60</u>		AC Thickness	12.25 Inch	
•••				•		
	,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,,		عود أيها شرق إدر الدر الدة الدر الدة الدر الدو الدو الدو الدو الدو الدو الدو الدو	4 4 7 5 7 7 7 7 7 2 2 2 2 2 2 2 2 2 2 2 2 2		الله الله الله الله الله الله الله الله
Rigid Pavement	Design	Actual T	$F_F = 14.79$	Minimur	$n TF_F = \underline{5.02}$	
-	_		Extended Lai	ne <u>10.25</u>	Inch	
	15' Panel F	CC Thickness		Partition of the state of the s	:• ·	
				er 0	Inch	
		ΥT	ntied Should		Inch	
		U	iiiioa biioaia	👡 Papara Su st iliti anno	(

RIGID PAVEMENT

Date: 21-Mar-12	Route IL 19 @			
Quantities by SIP	Checked by:	Section <u>32 WRS-5</u>		
Unit Prices b	Checked by:	<u>DuPage</u> County		
Net Length	878 Lin. Ft. = 0.17 Mi	es		
Number Lanes	4 Urhan X	Rural		

ITEMIZED CONSTRUCTION COST

	-		-	<u>Unit</u>	<u>Total</u>
<u>Quantity</u>	<u>Units</u>	Item		<u>Cost</u>	<u>Cost</u>
4683	Sq. Yds.	10 Inch Jointed PCC	@	\$39.02	<u>\$182,731</u>
4975	Sq. Yds.	4-Inch (Stabilized/Granular Subbase)	<i>@</i>	<u>\$16.00</u>	<u>\$79,600</u>
0	Sq. Yds.	PCC Shoulder	@	<u>\$0.00</u>	<u>\$0</u>
	Lin. Ft.	Pipe Underdrains	@		
<u>o</u>		Subbase Gran. Mat., Type C	@	<u>\$0.00</u>	<u>\$0</u>
<u> 1,756</u>	Lin. Ft.	100% Shoulder Joint Seal	@	<u>\$2.00</u>	<u>\$3,512</u>

Total Cost of Original Pavement Construction \$265.843

ITEMIZED MAINTENANCE AND REHABILITATION ACTIVITY COST

REHABILITATION ACTIVITY 1 - YEAR 10

<u>5</u> Sq. Yds.	0.1% Full Depth PCC Pavement Patching	@	\$130.00	<u>\$650</u>
	Total Cost of Rehabi			<u>\$650</u>

Sheet 2 of 5
RIGID PAVEMENT (Cont.)
Route IL 19 @ York Rd

Section

32 WRS-5

<u>DuPage</u> County

REHABILITATION ACTIVITY 2 - YEAR 15

Unit Cost Total Cost

9 Sq. Yds.

0.2% Full Depth PCC Pavement Patching @

\$130.00

\$1,170

Total Cost of Rehabilitation Activity 2

\$1,170

REHABILITATION ACTIVITY 3 - YEAR 20

			Unit Cost	Total Cost
94 Sq. Yds.	2% Full Depth PCC Pavement Patching	@	<u>\$0.00</u>	<u>\$12,220</u>
<u>0</u> Sq. Yds.	0.5% Full Depth PCC Pavement Patching	@	<u>\$85.00</u>	<u>\$0</u>
1756 Lin. Ft.	100% Longitudunal/ Shoulder Joint	@	<u>\$1.00</u>	<u>\$1,756</u>
	Routing & Sealing			•
2634 Lin. Ft.	100% Centerline Joint	@	<u>\$1.00</u>	<u>\$2,634</u>
	Routing & Sealing			
	Total Cost of Rehabi	litatio	n Activity 3	<u>\$16,610</u>

* . *				Sheet 3 of 5
		RI	GID PAVEN	IENT (Cont.)
		Route	<u>IL 1</u>	<u>9 @ York Rd</u>
•		Section		<u>32 WRS-5</u>
•			<u>DuPage</u>	County
REHABILITATION ACTI	VITY 4 - YEAR 25			
			Unit Cost	Total Cost
<u>140</u> Sq. Yds.	3.0% Full Depth PCC Pavement Patching	@	<u>\$130.00</u>	<u>\$18,200</u>
<u>0</u> Sq. Yds.	1.0% Full Depth PCC Pavement Patching	@	<u>\$85.00</u>	<u>\$0</u>
2 24. 2 3			-	•
	Total Cost of Rehabi	litation	Activity 4	<u>\$18,200</u>
REHABILITATION ACTI	VITY 5 - YEAR 30		•	
KEHADILITATION ACT	VIII 5 IEMICO.		Unit Cost	Total Cost
<u>187</u> Sq. Yds.	3.0% Full Depth PCC Pavement Patching	@	\$85.00	<u>\$0</u>
<u>107</u> Sq. Yds. <u>0</u> Sq. Yds.	1.0% Full Depth PCC Pavement Patching	@	\$11.85	<u>\$55,494</u>
<u>o</u> 5q. 14s. <u>4,683</u> Sq. Yds.	Policy HMA Overlay - Pavement	@	\$11.85	\$55,494
<u>4,005</u> 5q. 1ds. <u>0</u> Sq. Yds.	Policy HMA Overlay - Shoulder	@	\$11.85	<u>\$0</u>
<u>v</u> 54. 143.	Tolley III-III o tollay Blio II-II-I			•
	Total Cost of Rehabi	litation	Activity 5	<u>\$79,804</u>
REHABILITATION ACTIV	UTV 6 - VEAR 25		•	
KENADILITATION ACTI	VIII 0 - ILAN 33		Unit Cost	Total Cost
<u>1,756</u> Lin. Ft.	100% Longitudinal Shoulder Joint	@	\$1.00	<u>\$1,756</u>
<u>1,730</u> Lill, ft.	Routing & Sealing	-		
<u>2634</u> Lin. Ft.	100% Centerline Joint	@	\$1.00	<u>\$2,634</u>
<u>2034</u> bill PC	Routing & Sealing	J		•
<u>1,756</u> Lin. Ft.	50% Random Crack	@	\$1.00	\$1,756
<u>1,750</u> Lill. Ft.	Routing & Sealing - Assume 100ft/station			
1,124 Lin. Ft.	40% Reflective Transverse Crack	@	\$1.00	\$1,124
1,124 Lill. 14.	Routing & Sealing	•	<u></u>	
<u>5</u> Sq. Yds.	0.1% Partial-Depth Pavement Patching		\$130.00	<u>\$650</u>
<u>5</u> 24. 142.	(Mill & Fill Surface-Interstates; Mill & Fill	2.5in. N		ates)
	(PAIN OF I III DALIAGO HILOIDAGO) AAAA	,		-
	Total Cost of Rehabi	litation	Activity 6	<u>\$7,920</u>
	Total dope of House			

Sheet 4 of 5
RIGID PAVEMENT (Cont.)
ute <u>IL 19 @ York Rd</u>

Route

Section

32 WRS-5

<u>DuPage</u> County

REHABILITATION ACTIVITY 7 - YEAR 40

			unit cost	Total Cost
<u>23</u> Sq. Yds.	0.5% Full Depth PCC Pavement Patching	ø	<u>\$130.00</u>	<u>\$2,990</u>
23 Sq. Yds.	0.5% Partial Depth Pavement Patching	@	<u>\$130.00</u>	<u>\$2,990</u>
	(Mill & Fill Surface-Interstates; Mill & Fill 2	.5in. l	Ion-Intersta	ites)
1,686 Lin. Ft.	60% Reflective Transverse Crack	@	<u>\$1.00</u>	<u>\$1,686</u>
	Routing & Sealing			
1,756 Lin. Ft.	50% Random Crack	@	<u>\$1.00</u>	<u>\$1,756</u>
·	Routing & Sealing - Assume 100ft/station			
1,756 Lin. Ft.	100% Longitudunal/ Shoulder Joint	@	<u>\$1.00</u>	<u>\$1,756</u>
	Routing & Sealing			
2,634 Lin. Ft.	100% Centerline Joint	@	<u>\$1.00</u>	<u>\$2.634</u>
	Routing & Sealing			
	Total Cost of Rehabili	tation	Activity 7	<u>\$13,812</u>

Sheet 5 of 5 RIGID PAVEMENT (Cont.)

Route

IL 19 @ York Rd

Section

32 WRS-5

DuPage County

ANNUAL COST DETERMINATION

Present Worth Calculation:

Total (Cost of Original Pav	ement Construc	ction	<u>\$265,843</u>
Present Worth of Rehab Activity 1	\$650	x 0.7441 =	<u>\$484</u>	
Present Worth of Rehab Activity 2	<u>\$1,170</u>	x 0.6419 =	<u>\$751</u>	ŧ
Present Worth of Rehab Activity 3	<u>\$16,610</u>	x 0.5537 =	<u>\$9,197</u>	
Present Worth of Rehab Activity 4	<u>\$18,200</u>	$ \times 0.4776 = $	<u>\$8.692</u>	
Present Worth of Rehab Activity 5	<u>\$79,804</u>	x 0.4120 =	<u>\$32,879</u>	
Present Worth of Rehab Activity 6	<u>\$7,920</u>	x 0.3554 =	<u>\$2,815</u>	
Present Worth of Rehab Activity 7	<u>\$13,812</u>	x 0.3066 =	<u>\$4,235</u>	

Total Life Cycle Cost (Present Worth)

<u>\$59.053</u>

Annual Cost Per Mile Calculation

Total PW x CRF_n/ Length x0.04079/ 0.17 \$59,053 Mi. = Annual Cost / Year-Mile \$77.956 per Yr.-Mi.

FLEXIBLE PAVEMENT

Date:	21-Mar-12				Route IL 19	<u>@ York Rd</u>
Quantities by	SIP		Checked by:		Section 32 WI	<u> </u>
Unit Prices by	<u>TM</u>		Checked by:		<u>DuPage</u>	County
•	Net Length	. <u>878</u>	Lin. Ft. =	<u>0.17</u>	Miles	
Nu	mber Lanes	. <u>4</u>	Urban	<u>X</u>	Rural	
e		Single	Lane Paving	<u>X</u>	Dual Lane Paving	
						•

ITEMIZED CONSTRUCTION COST

				<u>Unit</u>	<u>Total</u>
Quantity	<u>Units</u>	<u>Item</u>		<u>Cost</u>	<u>Cost</u>
4,683	Sq. Yds.	Class I Surface Course	@	<u>\$11.85</u>	<u>\$55,494</u>
4,683	Sq. Yds.	Class I Binder Course	@	<u>\$29.98</u>	<u>\$140,396</u>
0	Sq. Yds.	Stabilized Shoulders	@	<u>\$0.00</u>	<u>\$0</u>
	Lin. Ft.	Pipe Underdrains	@		•
<u>0</u>		Subbase Gran. Matl., Type C	@	<u>\$0.00</u>	<u>\$0</u>
<u>4.683</u>	Sq. Yds.	Poly Binder	@	<u>\$10.97</u>	<u>\$51,373</u>

Total Cost of Original Pavement Construction \$247.263

ITEMIZED MAINTENANCE AND REHABILITATION ACTIVITY COST

REHABILITAT	ION ACTIV	ITY 1 - YEAR 5		<u>Unit</u> <u>Cost</u>	<u>Total</u> <u>Cost</u>
<u>483</u>	Lin. Ft.		@	<u>\$1.00</u>	<u>\$483</u>
		Sealing (Assume 110ft/station)			
<u> 1756</u>	Lin. Ft.	100% Longitudinal Shoulder Joint	@	<u>\$1.00</u>	<u>\$1,756</u>
		Routing & Sealing			
<u> 2634</u>	Lin. Ft.	100% Centerline Joint Rounting & Sealing	@	<u>\$1.00</u>	<u>\$2,634</u>
<u>5</u>	Sq. Yds.	0.1% Partial-Depth Pavement Patching	@	<u>\$90.00</u>	<u>\$450</u>
parties	•	Mill & Fill Surface			

Total Cost of Rehabilitation Activity 1 \$5,323

8					Sheet 2 of 5	วี
•		·	FLEXIE	BLE PAVEN	IENT (Cont.))
			Route	<u>IL 1</u>	9 @ York Ro	<u>1</u>
			Section		<u>32 WRS-5</u>	<u>:</u>
				<u>DuPage</u>	County	
REHABILI	TATION ACT	TVITY 2 - YEAR 10		<u>Unit</u>	<u>Total</u>	
	-		•	<u>Cost</u>	<u>Cost</u>	
	23 Sq. Yds	s. 0.5% Partial-depth HMA Pavement	@	<u>\$90.00</u>	<u>\$2,070</u>	
Territoria		Patching - Mill & Fill Surface				
4	<u>83</u> Lin. Ft	. 50% Random/Thermal Crack Routing	@	<u>\$1.00</u>	<u>\$483</u>	
		& Sealing (Assume 110ft/station)	· ·			
<u>17</u>	<u>56</u> Lin. Ft	. 100% Longitudinal Shoulder Joint	@	<u>\$1.00</u>	<u>\$1.756</u>	
		Routing & Sealing				
<u> 26</u>	<u>34</u> Lin. Ft	. 100% Centerline Joint Rounting & Seali	ng @	<u>\$1.00</u>	<u>\$2.634</u>	
		Total Cost of Reha	bilitation A	Activity 2	<u>\$6,943</u>	
		:				
REHABILI'	TATION ACT	IVITY 3 - YEAR 15	•	<u>Unit</u>	<u>Total</u>	
			_ •	Cost	Cost	
<u>4.68</u>	<u>33</u>		@	<u>\$1.75</u>	<u>\$8.195</u>	
4	<u> 17</u> Sq. Yds		@	<u>\$90.00</u>	<u>\$4,230</u>	
		(Mill & Fill Addition 2.00in.)	_	440200	ATT 446	
<u>52</u>	<u>24</u> Sq. Yds		@	<u>\$105.80</u>	<u>\$55,441</u>	
		Shoulder				

Total Cost of Rehabilitation Activity 3

\$67,866

			. • • • •			•
				•		Sheet 3 of 5
				FLEXII	BLE PAVEN	MENT (Cont.)
			•	Route	<u>IL 1</u>	9 @ York Rd
				Section		<u>32 WRS-5</u>
				٠	<u>DuPage</u>	County
					<u>Unit</u>	<u>Total</u>
REHA	BILITA	TION ACTIV	/ITY 4 - YEAR 20		Cost	<u>Cost</u>
	<u> 1756</u>	Lin. Ft.	100% Longitudinal Shoulder Joint	@	<u>\$1.00</u>	<u>\$1,756</u>
			Routing & Sealing	•		
•	<u> 2634</u>	Lin. Ft.	100% Centerline Joint Rounting & Sealing	g @	<u>\$1.00</u>	<u>\$2.634</u>
	<u>483</u>	Lin. Ft.	50% Random/Thermal Crack Routing	@	<u>\$1.00</u>	<u>\$483</u>
			& Sealing (Assume 110ft/station)		•	
	<u>5</u>	Sq. Yds.	0.1% Partial-Depth HMA Pavement	@	<u>\$90.00</u>	<u>\$450</u>
			Patching (Mill & Fill Surface)			
			Total Cost of Rehab	ilitation .	-	<u>\$5,323</u>
					<u>Unit</u>	<u>Total</u>
REHA	BILITAT	TION ACTIV	TTY 5 - YEAR 25		<u>Cost</u>	<u>Cost</u>
	<u> 1756</u>	Lin. Ft.	100% Longitudinal Shoulder Joint	@	<u>\$1.00</u>	<u>\$1.756</u>
			Routing & Sealing			
	<u> 2634</u>	Lin. Ft.	100% Centerline Joint Rounting & Sealing	g @	<u>\$1.00</u>	<u>\$2,634</u>
	<u>483</u>	Lin. Fţ.	50% Random/ Thermal Crack Routing	@	<u>\$1.00</u>	<u>\$483</u>
			& Sealing (Assume 110ft/station)			_
	<u>23</u>	Sq. Yds.	0.5% Partial-Depth Pavement Patching	@	<u>\$90.00</u>	<u>\$2.070</u>
			(Mill & Fill Surface)			
			Total Cost of Rehabi	litation A	-	<u>\$6,943</u>
			•		<u>Unit</u>	<u>Total</u>
REHA	BILITAT	ION ACTIV	TTY 6 - YEAR 30		<u>Cost</u>	<u>Cost</u>
	<u>4,683</u>	Sq. Yds.	2.00in. Milling (Pavement only-Std Design		<u>\$1.75</u>	<u>\$8,195</u>
			Pavement & Shoulder-Limiting Strain Crit	eria Des		
	<u>94</u>	Sq. Yds.	2.0% Partial-Depth HMA Pavement	@	<u>\$90.00</u>	<u>\$8,460</u>
			Patching (Mill & Fill Additional 2.00in. All			**
	<u>0</u>	Sq. Yds.	1.0% Full-Depth HMA Shoulder Patching	@	<u>\$90.00</u>	<u>\$0</u>
			(Mill & Fill Surface-Standard Design			
			Mill & Fill Additional 2.00inLimiting Stra			
	<u>983</u>	Tons	HMA Overlay Pvmt (3.75in Std Design	@	<u>\$105.80</u>	<u>\$104,005</u>
		•	2.00inLimiting Strain Criterion Design)	_		± a
	<u>0</u>	Tons	HMA Overlay Shoulder (1.75in Standard		<u>\$105.80</u>	<u>\$0</u>
			Design; 2.00inLimiting Strain Criterion I			****
			Total Cost of Rehabi	litation A	Activity 6	<u>\$120,660</u>

REHABILITATION ACTIVITY 7 - YEAR 35		·			FLEXIB Route Section	LE PAVEMI	@ York Rd 32 WRS-5
1756	RE:	HABILITAT	ION ACTIV	ITY 7 - YEAR 35		<u>Unit</u>	<u>Total</u>
Routing & Sealing Seal			· ·			<u>Cost</u>	<u>Cost</u>
Routing & Sealing 2634 Lin. Ft. 100% Centerline Joint Rounting & Sealing @ \$1.00 \$2.634		1756	Lin. Ft.	100% Longitudinal Shoulder Joint	@	<u>\$1.00</u>	<u>\$1,756</u>
2634 Lin. Ft. 100% Centerline Joint Rounting & Sealing @ \$1.00							
A83		2634	Lin. Ft.	•	@	<u>\$1.00</u>	<u>\$2,634</u>
**Sealing (Assume 110ft/station) 5		-				\$1.00	<u>\$483</u>
Sq. Yds. 0.1% Partial-Depth HMA Pavement @ \$90.00 \$450 Patching (Mill & Fill Surface) Total Cost of Rehabilitation Activity 7 \$5.323 REHABILITATION ACTIVITY 8 - YEAR 40 Unit Total Cost Cost Cost Cost Cost Routing & Sealing Lin. Ft. 100% Longitudinal Shoulder Joint @ \$1.00 \$1.756 Routing & Sealing Cisingle Lane and Dual Lane Paving) 483 Lin. Ft. 50% Random/ Thermal Crack Routing @ \$1.00 \$483 & Sealing (Assume 110ft/station) 23 Sq. Yds. 0.5% Partial-Depth Pavement Patching @ \$90.00 \$2.070 (Mill & Fill Surface)							
Patching (Mill & Fill Surface) Total Cost of Rehabilitation Activity 7 \$5,323		5	Sa. Yds.	- · · · · · · · · · · · · · · · · · · ·	@	\$90.00	<u>\$450</u>
REHABILITATION ACTIVITY 8 - YEAR 40 REHABILITATION ACTIVITY 8 - YEAR 40 1756 Lin. Ft. 100% Longitudinal Shoulder Joint @ \$1.00 \$1.756 Routing & Sealing 2634 Lin. Ft. 100% Centerline Joint Rounting & Sealing @ \$1.00 \$2.634 (Single Lane and Dual Lane Paving) 483 Lin. Ft. 50% Random/ Thermal Crack Routing @ \$1.00 \$483 & Sealing (Assume 110ft/station) 23 Sq. Yds. 0.5% Partial-Depth Pavement Patching @ \$90.00 \$2.070 (Mill & Fill Surface)		Ž.	5q. 145.				
1756 Lin. Ft. 100% Longitudinal Shoulder Joint @ \$1.00 \$1,756					itation A	activity 7	<u>\$5,323</u>
1756 Lin. Ft. 100% Longitudinal Shoulder Joint @ \$1.00 \$1,756							
1756 Lin. Ft. 100% Longitudinal Shoulder Joint @ \$1.00 \$1.756 Routing & Sealing 2634 Lin. Ft. 100% Centerline Joint Rounting & Sealing @ \$1.00 \$2.634 (Single Lane and Dual Lane Paving) 483 Lin. Ft. 50% Random/ Thermal Crack Routing @ \$1.00 \$483 & Sealing (Assume 110ft/station) 23 Sq. Yds. 0.5% Partial-Depth Pavement Patching @ \$90.00 \$2,070 (Mill & Fill Surface)	REI	HABILITATI	ON ACTIVI	ITY 8 - YEAR 40		<u>Unit</u>	<u>Total</u>
Routing & Sealing 2634 Lin. Ft. 100% Centerline Joint Rounting & Sealing @ \$1.00 \$2.634 (Single Lane and Dual Lane Paving) 483 Lin. Ft. 50% Random/ Thermal Crack Routing @ \$1.00 \$483 & Sealing (Assume 110ft/station) 23 Sq. Yds. 0.5% Partial-Depth Pavement Patching @ \$90.00 \$2,070 (Mill & Fill Surface)						<u>Cost</u>	<u>Cost</u>
2634 Lin. Ft. 100% Centerline Joint Rounting & Sealing @ \$1.00 \$2.634 (Single Lane and Dual Lane Paving) 483 Lin. Ft. 50% Random/ Thermal Crack Routing @ \$1.00 \$483 & Sealing (Assume 110ft/station) 23 Sq. Yds. 0.5% Partial-Depth Pavement Patching @ \$90.00 \$2,070 (Mill & Fill Surface)		1756	Lin. Ft.	100% Longitudinal Shoulder Joint	@	<u>\$1.00</u>	<u>\$1,756</u>
2634 Lin. Ft. 100% Centerline Joint Rounting & Sealing @ \$1.00 \$2.634 (Single Lane and Dual Lane Paving) 483 Lin. Ft. 50% Random/ Thermal Crack Routing @ \$1.00 \$483 & Sealing (Assume 110ft/station) 23 Sq. Yds. 0.5% Partial-Depth Pavement Patching @ \$90.00 \$2,070 (Mill & Fill Surface)				Routing & Sealing			
(Single Lane and Dual Lane Paving) 483 Lin. Ft. 50% Random/ Thermal Crack Routing @ \$1.00 \$483 & Sealing (Assume 110ft/station) 23 Sq. Yds. 0.5% Partial-Depth Pavement Patching @ \$90.00 \$2,070 (Mill & Fill Surface)		2634	Lin. Ft.	100% Centerline Joint Rounting & Sealing	@ .	<u>\$1.00</u>	<u>\$2,634</u>
483 Lin. Ft. 50% Random/ Thermal Crack Routing @ \$1.00 \$483 & Sealing (Assume 110ft/station) 23 Sq. Yds. 0.5% Partial-Depth Pavement Patching @ \$90.00 \$2,070 (Mill & Fill Surface)							
& Sealing (Assume 110ft/station) 23 Sq. Yds. 0.5% Partial-Depth Pavement Patching @ \$90.00 \$2,070 (Mill & Fill Surface)		483	Lin. Ft.	•	@	<u>\$1.00</u>	<u>\$483</u>
23 Sq. Yds. 0.5% Partial-Depth Pavement Patching @ <u>\$90.00</u> <u>\$2,070</u> (Mill & Fill Surface)		<u></u>		•			
(Mill & Fill Surface)	-	23	Sa. Yds.		@	\$90.00	<u>\$2,070</u>
		 -	4	•			
20002 0000 77 00000 7					itation A	ctivity 8	<u>\$6,943</u>

Sheet 5 of 5

FLEXIBLE PAVEMENT (Cont.)

Route

IL 19 @ York Rd

Section

32 WRS-5

DuPage County

ANNUAL COST DETERMINATION

Present Worth Calculation:

Total Cos	t of Original P	avement Construc	tion	<u>\$247,263</u>
Present Worth of Rehab Activity 1	<u>\$5,323</u>	x 0.7441 =	<u>\$4,592</u>	•
Present Worth of Rehab Activity 2	\$6,943	x 0.6419 =	<u>\$5,166</u>	•
Present Worth of Rehab Activity 3	\$67,866	x 0.5537 =	<u>\$43,563</u>	
Present Worth of Rehab Activity 4	\$5,323	$\times 0.4776 =$	<u>\$2,947</u>	
Present Worth of Rehab Activity 5	\$6,943	$\times 0.4120 =$	<u>\$3,316</u>	

Present Worth of Rehab Activity 4 $\frac{\$5,323}{\$6,943}$ $\times 0.4776 = \frac{\$2,947}{\$3,316}$ Present Worth of Rehab Activity 5 $\frac{\$6,943}{\$120,660}$ $\times 0.3554 = \frac{\$49,712}{\$120,660}$ Present Worth of Rehab Activity 7 $\frac{\$5,323}{\$5,323}$ $\times 0.3066 = \frac{\$1,892}{\$1,892}$

Present Worth of Rehab Activity 8 $\frac{$6,943}{}$ $\times 0.3066 = \frac{$2,129}{}$

\$113.317

Total Life Cycle Cost (Present Worth)

Annual Cost Per Mile Calculation

Total PW $\times CRF_n$ Length $\frac{$113,317}{}$ $\times 0.04079$ / 0.17 Mi.

= Annual Cost / Year-Mile \$86,518 per Yr.-Mi.

MATERIAL TYPE/PERCENTAGE PCC 10.98%

11.19.@YorkR 11.19. 32.WRS-5	d 21-Mar-12 11:04 AM	MAIN	MAINTENANCE COSTS: Activity 1 YEAR 10			UNIT PRICE	COST	PW.
Vork Rd	rung in			PAVEMENT:PATCHING 0.1% (SQ YDS)	40	\$130.00	\$650	
	= 0.17	· MILES	· Activity 2 YEAR 15	PAVEMENT PATCHING 0.2% (SQ YDS)	6	\$130,00	\$650	\$484
WVERAGE LANE WOTH (FT) NUMBER OF LANES NUMBER OF SHLORE WOTH (FT) 4 OF CHAIRE WITH (FT) 4 OF CHAIRE WITH THAFFIC FACTORS MINIMUM THAFFIC FACTORS	·		Aolivily 3 YEAR 20	PAVEMENT PATCHING 2,0% (SQ. YDS) SHOULDER PATCHING 0,5% (SQ. YDS) SHLDR JT ROUT & SEAL 100% (LF) CENTERLINE JT ROUT & SEAL 100% (LF)	94 0 0 7.756 2,634	\$130.00 \$85.00 \$1.00 \$1.00	\$1,170 \$12,220 \$0 \$1,766 \$2,634	\$751
RIGID- 5.02 PV 30798 SU- 2832 MU- 31.770	Percentages 67.00%		Activity 4 YEAR:25	5 PAVEMENT PATCHING 3.0% (SQ YDS) SHOULDER PATCHING 1.0% (SQ YDS)	140	\$130.00	\$16,610 \$18,200 \$0	\$8,187
INITIAL COSTS PAVEMENT (SO YOS) STAG SUBBASE (SO YOS) SHOULDERS (SO YOS) SHOULDERS SEAL (HI FT) 1788 1786 1786 1786 1786 1786 1786 1787	UNIT PRICE UNIT PRICE 5 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	COST \$162,731 \$73,800 \$0 \$13,512 \$0 \$0 \$0	Activity 5 YEAR 30	9 PAREMENT PATCHING 4.0% (SQ. YDS) SHOULDER PATCHING 1.5% (SQ. YDS) POLICY HING OVERLAY OVINT (SQ. YDS) POLICY HINA OVERLAY SHLDR. (SQ. YDS)	. 187 0 4,883	\$130.00 \$85.00 \$11.86 \$11.85	\$18,200 \$24,310 \$0 \$55,494 \$0	\$8,692
CONSTRUCT	INITIAL COST TATION COST	\$285,843 \$59,053	Activity 6 YEARS 35	6 5 SHIDR JT ROUT & SEAL 100% (LF) CENTEDINE WOANT 9 0001 A004, 100	1,758	2.2 8.2 8.3	\$79,804	\$32,879
TOTALI	TOTAL LIFE CYCLE COST (PW) ANNUAL COST PER MILE	\$324,896 \$77,856		CENTERNEY IN TO IS SELE LUDW (LF) RANDOM CRACK ROUT & SEAL 50% (LF) REFL TRANS CRACK ROUT & SEAL 40% PARTIAL PVMT PATCH 0.1% (SQ YDS)	2,634 1,756 1,124 6	\$1.00 \$1.00 \$130.00	\$2,634 \$1,756 \$1,124 \$850	•
MAINTENANCE COSTS: TEM SHOULDER PATCHING (SA YDS) SHUDR, JI ROUT & SE'AL (LP) CENTERINE JI ROUT & SE'AL (LP) POLICY HIAN OVERLAY PIWIT (SO YDS) POLICY HIAN OVERLAY SHIDR (SO YDS) RANDOM CRACK ROUT & SEAL (LF) RANDOM CRACK ROUT & SEAL (LF)		UNIT COST 8450.00 1510.00 1	Activity 7. YEAR 40'	7. PAVEMENT PATCHING-0.5% (SQ YDS) SHOULDER RYCHING 0.5% (SQ YDS) SHET, TRANS CRACK ROUT & SEAL 60% RANDOM CRACK ROUT & SEAL 60% (LF) SHUDR JT ROUT & SEAL 100% (LF) CENTERLINE JT ROUT & SEAL 100% (LF)	23 1,686 1,756 1,756 2,634	\$130.00 \$130.00 \$1.00 \$1.00 \$1.00 \$1.00	\$7,920 \$2,880 \$2,990 \$1,766 \$1,768 \$1,768	\$2,815
PARTIAL PVMT PATCH (SQ YDS)		1250 (2010) (2010) (2010) (2010) (2010) (2010)			!		\$13,812	*4 ,235
					Total Reh	Total Rehabilitation Cost (Present Worth)	Present Worth)	859,053

Ad	-	\$4,592	\$5,166		\$43,563		\$2,947	\$3,316		\$49,712	\$1,892	.* .	\$2,129
cost	\$483 \$1,756 \$2,634 \$450	\$5,323 \$2,070 \$483 \$1,756	\$2,634	\$8,195 \$4,230 \$55,441	\$67,886	\$2,634 \$483 \$450	\$5,323 \$1,756 \$2,634 \$483 \$2,070	36,943	\$8,195 \$8,480 \$0 \$104,003	\$120,660 \$1,758 \$2,834 \$483 \$483	\$5,323	\$1,758 \$2,634 \$483 \$2,070	\$8,943
T PRICE	\$1.00 \$1.00 \$1.00 \$90.00	\$90,00 \$1,00 \$1,00	80'18	\$1,75		\$4.00 \$4.00 \$0.00	\$1.00 \$1.00 \$1.00 \$90.00		\$1.75 \$90.00 \$90.00 \$105.80	\$1.00 \$1.00 \$1.00 \$80.00		\$1.00 \$1.00 \$1.00 \$90.00	l
QUANTITY UNIT PRICE	483 1,756 2,634 5	23 483 1,758	2,834	4,683 47 524	. 4	2,634 483 5	1,756 2,634 483 23		4,683 94 0 983	1,756 2,634 483	•	1,756 2,634 .483 .23	
FULL DEOTH FLEXIBLE PAVEMENT MAINTENANCE COSTS ITEM O	AGIMIN 1 YEAR 5 RANDTHERM CRACK ROUT 8 SEAL 50% (LF) SHLIPR JT ROUT 8 SEAL 100% (LF) CENTERLINE JT ROUT 8 SEAL 100% (LF) PARTIAL PUMT PATCH 0,1% (SQ YDS)	Activity 2 YEAR 10 PARTIAL PVMT PATCH 0.5% (SCI YOS) RANIOTHERM CPACK ROUT & SEAL 50% (LF) SHLDRY IROUT & SEAL 1,00% (LF) FOR THE PARTY OF THE PARTY	CENTEKLINE JI KOUT & SEAL 199% (LF)	ACHIVIDA YEAR 16 2" MILL PVMT & SHLDR 100% (SQ YDS) PARTIAL PVMT & SHLDR 100% (TONS) Z" OVERLAY PVMT & SHLDR 100% (TONS)	Activity 4 VEAR ON SHIPR IT ROLIT & SEAL 1010%, A EX	CENTERLINE JT ROUT & SEAL 100% (LF) RANDTHERM CRACK ROUT & SEAL 50% (LF) PARTIAL PVMT PATCH 0.1% (SQ YDS)	Activity 5 YEAR 25 SHLDR JT ROUT & SEAL 100% (LF) CENTERLINE JT ROUT & SEAL, 100% (LF) RANDTHERM CRACK ROUT & SEAL, 50% (LF) PARTIAL PUMIT PATCH 0.5% (SQ YDS)		ACIMIN 6 YEAR 30 2" MILL PVMT & SHLDR 100% (SQ YDS) YEAR 30 2" MILL PVMT PATCH 2.0% (SQ YDS) HMA SHLDR PATCHING 1.0% (SQ YDS) POLICY HMA OVERLAY PVMT (TONS) POLICY HMA OVERLAY SHLDR (TONS)	Adivity 7 YEAR 35 SHLDR JT ROUT & SEAL 100% (LF) CENTERLINE JT ROUT & SEAL 100% (LF) RANDTHERM CRACK ROUT & SEAL 50% (LF) PARTIAL PVINT PATCH 0.1% (SQ YDS)	,	AGNUNO YEAR O'SHLDR JT ROUT & SEAL 100% (LF) CENTERLINE JT ROUT & SEAL 100% (LF) RANDTHERM CRACK ROUT & SEAL 60% (LF) PARTIAL PVMT PATCH 0.5% (SQ YDS)	
EULL DE 21-Mar-12 11:04 AM ·		DUAL LANE					\$55,484 \$55,484 \$61,373 \$140,388 \$50	\$247,263			3105.00		
		1=RUBAI, 2=URBAN 1=Singre Lane, 2~Dual lane	ACTUAL	0.87 0.08 0.05			UNIT PRICE - 51186 31097 329,86	INITIAL COST (PW)	LIFE CYCLE COST (PW)			. 11.0%	
TRAFFIC FACTOR LESS THAN 15.0 (RURAL) TRAFFIC FACTOR LESS THAN 10.0 (RURAN) ROUTE. SECTION. 32 WRS-5 COLINY. DIPPAR	Vor Rd LENGTH (FT) LANE WIDTH (FT) OF LANES	ER WIDTH (FT) LOER WIDTH (FT) 3 RINES TH TH	FACTORS FLEXIBLE TO THE TOTAL OF THE THE THE TOTAL OF THE	1KAFFIC PV. 30798 SU. 2832 MU- 1770		SHOULDER OVERLAY THICKNESS	SURFACE (SQ. VDS) POLY BINDER (SQ. VDS) 4,883 4,883 HINDER (SQ. VDS) 4,883 SHOULDERS (SQ. VDS) SUBBASE GRAN MATL TY C (TONS)	CONSTRUCTION INITIAL COST (PW) TOTAI REHABII ITATION COST (PW)	Ki	RANDTHERM CRAOK ROUT & SEAL (LF) SHLDR.JT ROUT & SEAL (LF) SHLDR.JT ROUT & SEAL (LF) CAGNTERNIDEJ. TROUT & SEAL (LF) PARTIAL PVMT PATCH (SO YDS) Z" OVERLAY PVMT & SHLDR (TONS) Z" MILL PVMT ONLY (SO YDS) HMA SHOULDER PATCHING (SO YDS) HMA SHOULDER PATCHING (SO YDS)	POLICY HMA OVERLAY PVMT (TONS) POLICY HMA OVERLAY SHLDR (TONS)	MATERIAL TYPE/PERCENTAGE PCC	

\$113,317



2 or 3

6 or more

50%

32%

20%

50%

45%

40%

MECHANISTIC PAVEMENT DESIGN Date: 2/10/12 Spreadsheet by Uehle - Rev. 11/02 **INPUT** (Enter Data in Gray Shaded Cells) Comments: Fraffic cata for it, 19 at York Ro Route: FAU E2214L49 Section: 12/4/8/5 County: DuPage ADT Year Location: 1 19 at York R Designer: 100 32600 PACE Current: Facility Type #41 C Make State Route 37000 Future: # of Lanes = Structural Design Traffic % of ADT in Minimum Actual Actual %of ΔΠΤ ADT Total ADT Design Lane Road Class: P≡ 32% 87.0% PV= Ó 30,798 B 0% SĦ 45% su= *2*50 2,832 Subgrade Support Rating (SSR): 5.0% M = 45% MU = 750 1.770 Construction Year: 2012 35400 Struct. Design ADT = (2022)Design Period (DP) = 20 years FLEXIBLE & RIGID PAVEMENT CALCULATIONS AND ADDITIONAL INPUT Rigid Pavement Flexible Pavement 0.15 Cpv = 0.15Cpv = Csu = 144 133 Csu = Cmu = 696 Cmu = 483 14:79 (Actual ADT) TF rigid (Actual)= 11.09 (Actual ADT) TF flexible (Actual)= (Min ADT Fig 54-2C) 5.02 TF flexible (Min)= 3.56 (Min ADT Fig 54-2C) TF rigid (Min)= Use TF rigid = 14.79 Use TF flexible = 11.09 Shoulder or C. &G. AC Type = - 20 Rigid Pave Thick 10.00 in (Figure 54-4D) AC Mixture Tempurature = 80.0 deg. F (Figure 54-5C) Design AC Mixture Modulus (Eac)= 550 ksi (Figure 54-5D) Design Asphalt Concrete Microstrain = 48.3 (Figure 54-5E) Asphale Concrete Unickness = 16/25 in 16 gure (4-5); PAVEMENT DESIGN CH. 54 AND PAVEMENT DESIGN MANUAL **DESIGN TABLES FROM BD&E** Class IV Roads Class III Roads Class Roads Class II Roads # lanes or more
Part of a future 4 lanes of more
One-way Streets with ADT \$ 3500 2 Lanes 2 Lanes 2 lanes with ADT > 2000 (ADT 750 -2000) (ADT < 750) One way Street with ADT <= 3500 Class Table for Min. Str. Design Traffic (Fig 54-2C) One-Way Streets PV SII MU Facility Type 1500 ADT Class Interstate or Supplemental Freeway 500 Par Some Marked State Roote - - - 1. . - 1000 / 1000 0 - 350011 >3501 No Min No Min Unmarked State Route No Min Class Table for Traffic Factor ESAL Coefficients Rigid (Fig. 54-4C) 2 or 3 lanes Flexible (Fig. 54-5B) Cmu (not future 4 lane & Cmu Csu Csu Class Andrews and the second of the 132 50 482.56 not one-way street) ADT Class 112.06 385.44 135.78 567.21 11 384.35 0 - 749 IV 109.14 562.47 111 129.58 750 - 2000 Ш 109,14 384.35 IV(ADT>400) 127.75 555.90 >2000 11 78.84 IV(ADT<=400) 127.75 555.90 9.86 Percentage of ADT in Design Lane Figure 54-2B Urban Rural Р S M P S M Number of Lanes 100% 100% 100% 100% 100% 100% 1 Lane Ramp 50%

50%

22%

8%

45%


37%

50% 45%

40%

50%

37%




Note: Use of untied shoulder design requires BDE approval.

RIGID PAVEMENT DESIGN CHART (Mechanistic Design: SSR = Poor)

10 /4" PCC PAVEMENT (SOINTED)


Figure 54-4.E





Note: The minimum design HMA mixture temperature will be 73 °F.

HMA MIXTURE TEMPERATURE (Mechanistic Design: Flexible Pavement)


Figure 54-5.C








April 2011



COMPOSITE PAVEMENT DESIGN NOMOGRAPH (Class I Facilities)

Figure 54-6.A

April 2011



FLEXIBLE PAVEMENT DESIGN NOMOGRAPH (Modified AASHTO Design: Class | Facilities)

Figure 54-5.M

henesch	Comp. by:	Date:	Sheet	of
benesch engineers - scientists - planners	Project: Element:	1L 19 @ YORK		

14	19	WIDENING
Li		

FLEXISLE MECHANISTIC BIGID !

- 12" HMA PAVEMENT (FULL DEPTH)
 - d" POLY HAMA SURFACE COURSE, MIX F, NED
 - d'in Pory HMA BINDER CONREE, 12-19.0, N90
 - 74" HMA SINDER COLASE, IL-19.0 , NO
 - 12" AGG SUSEMOE IMP.

MODIFIED ASSHTD!

- 18" HMA PAVEMENT
 - d'g" HMA SURFACE
 - 15% HMA BASE
- 4" AGG. SUB CAMOR

COMPOSITE

- 13" PAVEMENT
 13" HAMA BURFACE, MIX F", NRO
 - 21/4" four HOTA BINDER, MEILL-19.0-, NED
 - 9" PCC BASE COURSE

"SEGMENTAL" EXISTING ?

First Cost Analysis of Widening Project

Date:

Quantities by: Unit prices by:

4/21/2012 SJP

SJP

Checked by: Checked by:

Net Length

969

Route

IL 19

.Section County

DuPage IL19 at York

Project Contract

· <u>-</u>		•	Mechanistic Flexible				
Area (Sg. Yd.)	Height (inches) Weight (Tons) Material				Unit Cost	Total	ITEM #
	,	. 0	HMA Surface Course, MIX "D" N50	@		\$0.00	4060333
		Ö	HMA Surface Course, MIX "D" N70	@		\$0.00	4060334
944	2	106	Poly HMA Surface Course, MIX "F" N90	- @	\$120	\$12,687.36	4050359
344		0	Poly HMA Surface Course, SMA N80	@	7 .	\$0.00	4060315
		0	HMA Binder course, IL-19, N50			\$0.00	4060308
		D D	HMA Binder course, IL-19, N70	@		\$0.00	4060308
944	8	423	HMA Binder course, IL-19, N90	e e	\$90	\$38,062.08	4060309
944	2.25	119	Poly HMA Binder course, IL-19, N90	e e	\$93	\$11,061.79	4060324
544	. 2.23	0	HMA Binder course, SMA, N80	, <u>@</u>	• •	\$0.00	4060314
944 .	. NA	NA NA	12" Aggregate Subgrade		\$16	\$15,104.00	Z000105
944 NA NA			Total			\$76,915.23	

			Composite				
Area (Sq. Yd.)	Height (inches)	Weight (Tons)	Material		Unit Cost	Total	ITEM#
raco (oq. rai)	· · · · · · · · · · · · · · · · · · ·	0	HMA Surface Course, MIX "D" N50	@		\$0.00	40603335
		0	HMA Surface Course, MIX "D" N70	@		\$0.00	40603340
944			Poly HMA Surface Course, MIX "F" N90	· @	\$110	\$11,630.08	40603595
· • • • • • • • • • • • • • • • • • • •			Poly HMA Surface Course, SMA N80	. @		\$0.00	40603153
944	2,25	119	Poly HMA Binder course, IL-19, N90		\$92	\$10,942.85	
944	. 9.25	NA .	PCC Base Course		\$48	\$45,312.00	35300410
944	NA.	NA .	4" Subgrade Aggregate Material Type B	. @	\$10	\$9,440.00	31101200
Total						\$77,324.93	